RUILDING SAFETY CERTIFICATE

	The Party of the Late of the L	
TO STATE OF THE ST		
n		

Dated: 14-03-2024

It is certified that the existing building ... Cherypushpa Certhal School (name of the building or premises) at Ayour (p.o) Punalur Taluk, bollans Revale (address) is having block(s)/Floor(s) as per details below:

Details of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3 floor	3 floor	-	-		-

The building is owned/occupied by Cheripushpa Central School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of M.D. Stu. Settion, Educated & roma perdagth (Name of Department/Govt.)
on. 11-03-2004 (date of inspection) in the presence of Fire Christy Chamuila Roby Region) Chempushpa Central School Mame and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from March 11, dod 4 for a period of ... One.... years in accordance with rule and subject to compliance of the specific conditions as appended.

School's man fanance works have been done proposly under normal weather Conditions the Structure is sound for conducting Classes.

Issued on 14-03-2024 at Edamwaded by Assistant Engineer * Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

AYOOR

Name: Solman J-s ASSISTANT ENGINEER

Designation: Account

Designation: Assistant Franciscon

Name & Address of Department

A Soft Stant Franciscon

Name & Address of Department

A Soft Stant Franciscon

Name & Address of Department

A Soft Stant Franciscon

Name & Address of Department

A Soft Stant Franciscon

Name & Address of Department

A Soft Stant Franciscon

Name & Address of Department

Name & Address of Departme Name & Address of Department Office: LID 861 Seekin Cokonalackes

4.

Cherupushpa Central School, Ayoor